

## **Siaran Pers/Press Release**

27 Mei/May 2019

### **Insiden di Pembangkit Listrik Tenaga Panas Bumi Unit 1 di Silangkitang/ Incident in Geothermal Power Plant Unit 1 Silangkitang**

**Jakarta-** Sarulla Operations Ltd melaporkan insiden kebakaran yang terjadi pada pukul 21:21 waktu setempat, 26 Mei 2019 di area Pembangkit Listrik Tenaga Panas Bumi Unit 1 Silangkitang (“**PLTP Unit 1 SIL**”), Sarulla Operations Ltd. Diidentifikasi bahwa ada kebocoran selang dan pentana terbakar oleh panas dari generator portabel yang digunakan untuk penerangan tambahan di dekat selang disaat kontraktor melepas pentana. Peristiwa ini terjadi selama pekerjaan pemeliharaan PLTP Unit 1 SIL, dengan jadwal pemadamaman tahunan dimulai 25-30 Mei 2019. Api dipadamkan pada sekitar pukul 22:00 malam dan memastikan daerah itu aman. Dipastikan tidak ada yang terluka dalam insiden dan PLTP Unit 1 SIL dalam keadaan aman.

Chief Executive Sarulla Operations Ltd, Hisao Nakano, mengatakan; “Kami segera bertindak untuk mengatasi situasi tersebut. Semua tindakan yang perlu diambil dan insiden itu diselesaikan dengan aman. Kami sangat menghargai tim pemadam kebakaran, masyarakat setempat dan semua pihak yang terlibat. Insiden ini merupakan pengingat bagi tim untuk melanjutkan fokus kami pada peningkatan standar HSE kami dan bekerja tanpa kecelakaan. Investigasi komprehensif sedang dilakukan untuk memahami keadaan dan memastikan kami belajar dari kejadian ini.

**Jakarta-** Sarulla Operations Ltd reported a fire incident which occurred at 21:21 pm, local time on May 26, 2019 at Geothermal Power Plant Unit 1 Silangkitang (“**PLTP Unit 1 SIL**”) area of Sarulla Operations Ltd. It was identified that there was a hose leak and the pentane caught on fire from heat from a generator portable using for additional lighting near the hose while contractor removing pentane. This incident happened during the PLTP Unit 1 SIL maintenance work, with the schedule of annual outage commenced 25-30 May 2019. The Fire was extinguished at around 22:00 pm and ensured the area was safe. It is confirmed that there were no injured in this incident and PLTP Unit 1 SIL is in safe condition.

Sarulla Operations Ltd Chief Executive, Hisao Nakano, said; “We immediately responded to overcome the situation. All necessary actions were taken and the incident was safely resolved. We really appreciate the fire extinguisher team, local community and all parties involved. This incident is a reminder to our team to continue our focus on improving our HSE standards and working towards a goal of zero accidents. A comprehensive investigation is underway to understand the circumstances and ensure we learn from this incident.

Contact person:

**Rangga Wirapasa**

V.P External Relations and Corporate Counsel Sarulla Operations Ltd

[Rangga.Wirapasa@sarulla-geothermal.com](mailto:Rangga.Wirapasa@sarulla-geothermal.com)

Sarulla Operations Ltd official website :

[www.sarullaoperations.com](http://www.sarullaoperations.com)